



## REFERENCE.

## SPECIAL HAZARDS.

NAMES of Manufactories, &c., are written on buildings, when there is sufficient space, and their construction classified by the same marks as on Dwellings. Other Specially Hazardous Risks are COLORED GREEN, the varying number of dots (brick) and crosses (frame) showing the comparative danger from fire by occupancy,



NOTE.—In classifying a building as a Special, its CONSTRUCTION is obliterated, necessitating a series of letters, as follows:



Store or Dwelling.

Store or Dwelling.

BRICK.							FRAME.		
A	Construction	1st class Warehouse.				G Construction = to 1st class			
В	66	= "	2nd	**		11			Store or Dw
C	46	= "	3rd	44		66		**	
D	**	= "	Ist	"Store or D'w'g.			H	••	= to 2nd class
$\mathbf{E}$	**	= "	2nd	61	**	**			Store or Dw
F	66	= "	3rd	**	66	64			



.....Frame

Bakeries (ovens in building). Breweries. Cooperages. Drug stores (retail, with privilege of compounding). Dyeing establishments. Fur dressers. Glass stainers. Hat finishers. Hay (open stock, loose). Lamp sellers (privilege for kerosene &c.) Laundries. Malt houses. Manufactories of Baskets, Bonnet-frames, Boots and shoes, Caps, Clothing, Combs, Envelopes, Feather dusters, Fringe &c., Gas fixtures, Gold pens, Hats, Hemp, Jewelry cases, Morocco, Paper bags, Pocket-books, Ruffling and ruches, Segars, Shirts, Tobacco, Umbrellas, Vinegar, Watches, Watch-cases, Writing ink. Map mounting and varnishing. Metal mills. Molasses houses. Photographers. Private stables. Smoke-houses. Tanneries. Tin-shops. Wheelwrights. Wire Smoke-houses. workers. Wool-pullers.

Brick .....



Bleaching works. Book-binderies. Brass and iron foundries. Coppersmiths. Cotton presses. Fulling mills. Junk shops. Letter-press printers. Lithographers. Livery and Cartmen's stables. Machine shops. Manufactories of Agricultural Implements. Artificial flowers, Brooms, Brushes, Carriages, Cedar-ware, Floor-cloth, Grates, Guns, Hoop-skirts, Jewelry, Lamps, Musical instruments, Oil-cloths, Paper boxes, Paper collars, Paper patterns, Patent Medicines, Plated ware, Rope and cordage, Safes, Silverware, Starch, Stoves, Tin cans, Upholstery. Oil stores (petroleum and products). Print works. Rag stores. Slaughter houses. Snuff mills. Type and stereotype foundries. (And generally buildings not occupied by workers of light wood).

Brick.....



.....Frame

Box repairing. Cabinet-making. Carpenters' shops. Distilleries. Flax mills. Flour or Grist mills. Japanuers. Lard refineries. Manufactories of Artificial hair, Bagging, Candles, Chairs, Clocks, Confectionery, India-rubber or gutta-percha, Ivory or lampblack, Looking-glass and Picture frames, Oiled clothing, Organs, Paper-hangings, Perfamery, Pianos, Soap, Trunks. Oil mills. Paper mills. Rectifying establishments. Tallow-melting or chandleries. Wholesale druggists (with compounding). Woolen mills. (And generally risks where much heat or light wood is used.)

Brick ....



.....Frame

Chemical laboratories. Coffee and Spice mills. Drug mills. Fireworks on sale, Match factories. Oil-boiling houses. Planing and Moulding mills. Printing-ink factories. Sash, blind and door factories. Saw mills. Tar-boiling houses. Turpentine distilleries. Varnish making. Window-shade factories.